

Bring the following items to the dock:

- Two spare hydraulic hoses cut to two meters
- A calibrated torque wrench with the 19 millimeter socket
- The signed confined-space permit