

Device Setup Guide

1. Connect the AC adapter to the laptop.
 2. Press the power button for two seconds.
 3. Open Settings and select Network.
- Figure 1. Port layout and adapter connection.

Wake on LAN Setup

1. Open Device Manager.
2. Right-click Ethernet and select Properties.
3. Enable Wake on Magic Packet.

Table 1. Required settings and expected values.